


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-216	Smoke	8/10/2009	ADS/TM	S19KK_049MH	Dry	Yes	601.72



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-216	Smoke	8/10/2009	ADS/TM	S19KK_049MH	Dry	Yes	601.72

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19KK_040G1	S19KK_040MH	S19KK_049MH	142.886	8
S19KK_004G1	S19KK_004MH	S19KK_049MH	83.0035	10
S19KK_049G1	S19KK_049MH	S19KK_066MH	273.161	10
S19KK_066G1	S19KK_066MH	S19KK_003MH	102.666	10

Observations & Photos

Obs_ID S1028-216-OB01

Address 2023 Payson St


Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19KK_049MH

Comments Smoke from cleanout in paved concrete in back yard. 2023 Payson St.



Picture \S1028-216-OB01-P01.jpg

Comments Back of house, 2023 Payson St.

Obs_ID S1028-216-OB02

Address 2017 Payson St


Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19KK_049MH

Comments Smoke from cleanout in paved concrete in back yard. 2017 Payson St.



Picture \S1028-216-OB02-P01.jpg

Comments Back of house, 2017 Payson St.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-216	Smoke	8/10/2009	ADS/TM	S19KK_049MH	Dry	Yes	601.72

Obs_ID S1028-216-OB03

Address 2015 Payson St


Status Private

Source Cleanout

Location Paved concrete

Nearest MH S19KK_049MH

Comments Smoke from above-ground cleanout in paved concrete in back yard. 2015 Payson St.



Picture \S1028-216-OB03-P01.jpg

Comments Back of house, 2015 Payson St.

Obs_ID S1028-216-OB05

Address 1938 Ridgehill Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_049MH

Comments Smoke from cleanout in back yard. 1938 Ridgehill Ave.



Picture \S1028-216-OB05-P01.jpg

Comments Back of house, 1938 Ridgehill Ave.

Obs_ID S1028-216-OB04

Address 1945 Clifton Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_049MH

Comments Smoke from cleanout in back yard. 1945 Clifton Ave.



Picture \S1028-216-OB04-P01.jpg

Comments Back of house, 1945 Clifton Ave.

Obs_ID S1028-216-OB06

Address 1926 Ridgehill Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_049MH

Comments Smoke from cleanout in back yard. 1926 Ridgehill Ave.



Picture \S1028-216-OB06-P01.jpg

Comments Back of house, 1926 Ridgehill Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-216	Smoke	8/10/2009	ADS/TM	S19KK_049MH	Dry	Yes	601.72

Obs_ID S1028-216-OB07

Address 1922 Ridgehill Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_003MH

Comments Smoke from cleanout in back yard. 1922 Ridgehill Ave.



Picture \S1028-216-OB07-P01.jpg

Comments Back of house, 1922 Ridgehill Ave.

Obs_ID S1028-216-OB08

Address 1917 Clifton Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_003MH

Comments Smoke from cleanout in back yard. 1917 Clifton Ave.



Picture \S1028-216-OB08-P01.jpg

Comments Back of house, 1917 Clifton Ave.